



<b>AUDI Q5: 1KAZ153</b>			
Vinnnumber:	<b>WAUZZZ8R6FA081008</b>	Versionname:	<b>2.0 TDI 100KW</b>
First Registrationdate:	<b>23/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>132175</b>	Power Kw:	<b>100</b>
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>3624</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		


<b>Options</b>	
Radio CD	Central consol F
GPS storage <b>HD</b>	Luggage cover
GPS storage	Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting <b>Headlighting Halogen</b>	
Type of GPS <b>GPS big screen color</b>	
Type of Lining <b>Lining fabrics</b>	
Type of climate control <b>Autom climate control</b>	

<b>Limited Technical Inspection</b>			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

<b>Degree of wear</b>				
Winter tyres:	<b>235/65/17/108 V LightMetal</b>			
	Fr.L.	<b>Uniroyal: 5 mm</b>	Fr.R.	<b>Uniroyal: 5 mm</b>
	Re.L.	<b>Uniroyal: 7 mm</b>	Re.R.	<b>Uniroyal: 7 mm</b>

<b>Assistance equipment</b>			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
<b>Total cost ex VAT</b>			<b>1872,48</b>
<b>Wing R R, Scratch(es), LI - Repair and paint (complete)</b>			<b>369,84</b>





Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Wing F L, Scratch(es), LI - Repair and paint (complete) 264,21



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Scratch(es), LI - Repair and paint (complete) 348,09



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete) 254,16

