


BMW 3: 1GTA542

Vinnumber:	WBA3D91080J414252	Versionname:	3 BER 316d 116PK
First Registrationdate:	22/04/2014	Fiscalpower:	
Expertise Mileage:	100801	Power Kw:	85
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance	OK	Parking lot:	1333
Maintenance	25000		
Maintenance	MEI 2019		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Rear parking sensors
GPS storage		
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	679,24
-------------------	--------

Outer backrest protection R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Door panel R R, Damaged, Smart repair	110,64
---------------------------------------	--------



Outer door handle F L, Scratch(es), Acceptable	0,00
--	------

<i>No pictures to display</i>	
Outer door handle F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Door R R, Bump(s) and scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Covering mid pillar L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Interior, Dirty, Cleaning	50,00



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

<i>No pictures to display</i>	
Bumper R, Damaged, LI - Repair and paint (complete)	211,80



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

<i>No pictures to display</i>	
Wing F L, Scratch(es), Acceptable	0,00

<i>No pictures to display</i>	
Door R R, Scratch(es), Acceptable	0,00

<i>No pictures to display</i>	
Front bumper, Damaged, LI - Repair and paint (complete)	211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------

