



AUDI A4: 1FAD056

Vinnumber:	WAUZZ8K1DA223460	Versionname:	A4 AVANT TDie 136PK
First Registrationdate:	3/05/2013	Fiscalpower:	
Expertise Mileage:	89456	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4228
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Sun Roof electric
GPS storage	CD	Panoramic roof
GPS storage		Central consol F
Windows electric F		Luggage cover
Windows electric R		Front parking sensors
Cruise Control		Rear parking sensors
Steering wheel multifunction		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 H LightMetal			
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 5 mm	Re.R.	Pirelli: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	0,00
-------------------	-------------

Wing F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	0,00
---	-------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	0,00
--	-------------



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 0,00



Ceiling, Deformed, Repair/replace (lump sum) 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 0,00



Sidewall panel RL, Scratch(es), Smart repair 0,00



Bumper grille, Strained , P - Check 0,00



Door R R, Scratch(es), LI - Repair and paint (complete) 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 0,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 0,00



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 0,00



Door panel trim R R, Deformed, P - Check 0,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 0,00



Sill outer R, Bump(s) and scratch(es), It - Spot repair 0,00



Rear wiper arm, Missing, E - Replace 0,00

