



|                         |                   |              |                         |
|-------------------------|-------------------|--------------|-------------------------|
| CITROEN C5: 1FH0848     |                   |              |                         |
| Vinnnumber:             | VF7RW9HD8DL513908 | Versionname: | C5 TOURER e-HDi Bus.GPS |
| First Registrationdate: | 1/07/2013         | Fiscalpower: | PI.BMP 113PK Aut        |
| Expertise Mileage:      | 151559            | Power Kw:    | 84                      |
| Bodytype:               |                   | Body color   | Brown                   |
| Gearbox:                | Automatic         | Paint type   | Metalic                 |
| Transmission:           | Front             | Rims summer  | Aluminium               |
| Fueltype:               | Diesel            | Oil level    | OK                      |
| Maintenance             | OK                | Parking lot  | 2130                    |
| Battery functioning     | Yes               |              |                         |
| Number of doors         | 5                 |              |                         |
| Number of seats         | 5                 |              |                         |
| Number head rests       | 5                 |              |                         |
| Rims summer             | Aluminium         |              |                         |
| Category                | Passenger Car     |              |                         |
| Oil level               | OK                |              |                         |

|                                |                         |
|--------------------------------|-------------------------|
| Options                        |                         |
| Radio CD                       | Central consol F        |
| GPS storage                    | Luggage cover           |
| GPS storage                    | HD Rear parking sensors |
| Windows electric F             |                         |
| Windows electric R             |                         |
| Cruise Control                 |                         |
| Steering wheel multifunctional |                         |
| Type of headlighting           | Headlighting Halogen    |
| Type of Lining                 | Lining leather          |
| Type of climate control        | Autom climate control   |

|                              |    |                     |     |
|------------------------------|----|---------------------|-----|
| Limited Technical Inspection |    |                     |     |
| Airco functioning            | OK | Battery functioning | Yes |
| Tires wear profile           | OK | Power steering      | Yes |
| Idle position                | OK | Sound engine        | OK  |
| Engine startingtime          | OK | Clutch test         | OK  |
| Exhaust gass                 | OK | Wiper fluid level   | OK  |
| Handbrake                    | OK | Transmission        | OK  |
|                              |    | Lighting            | OK  |
|                              |    | Wiperblades         | OK  |

|                |                           |                   |       |
|----------------|---------------------------|-------------------|-------|
| Degree of wear |                           |                   |       |
| Winter tyres:  | 225/60/16/98 H LightMetal |                   |       |
|                | Fr.L.                     | Continental: 5 mm | Fr.R. |
|                |                           | Continental: 5 mm |       |
|                | Re.L.                     | Continental: 4 mm | Re.R. |
|                |                           | Continental: 4 mm |       |

|                                                         |     |      |        |
|---------------------------------------------------------|-----|------|--------|
| Assistance equipment                                    |     |      |        |
| Spare wheel                                             | Yes | Jack | Yes    |
| Total cost ex VAT                                       |     |      | 211,80 |
| Alloy rim R R, Scratch(es), Acceptable                  |     |      | 0,00   |
| No pictures to display                                  |     |      |        |
| Bumper R, Scratch(es), LI - Repair and paint (complete) |     |      | 211,80 |



|                                       |  |  |      |
|---------------------------------------|--|--|------|
| Door F L, Bump(s), Acceptable         |  |  | 0,00 |
| No pictures to display                |  |  |      |
| Windscreen, Stone chip(s), Acceptable |  |  | 0,00 |
| No pictures to display                |  |  |      |