



BMW 3: 1FBP143			
Vinnnumber:	WBA3D910X0F405684	Versionname:	3 BER 316d 116PK
First Registrationdate:	16/05/2013	Fiscalpower:	
Expertise Mileage:	136050	Power Kw:	85
Bodytype:	Berline	Body color	White
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1705
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options	
Radio CD	Central consol F
GPS storage	Luggage cover
GPS storage	HD Rear parking sensors
Windows electric F	
Windows electric R	
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Summer tyres:	205/60/16/92 W LightMetal			
	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			0,00
Wing R R, Bump(s), Acceptable			0,00
No pictures to display			
Alloy rim F L, Scratch(es), Acceptable			0,00
No pictures to display			
Wing F L, Bump(s), Acceptable			0,00
No pictures to display			
Door R R, Bump(s), Acceptable			0,00
No pictures to display			
Door panel F L, Damaged, Acceptable			0,00
No pictures to display			
Tailgate, No damage, Acceptable			0,00
No pictures to display			
Door F R, Bump(s), Acceptable			0,00
No pictures to display			

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display