



BMW 5: 1EQ157				
Vinnnumber:	WBAXB31000DW54012	Versionname:	5 TOURING 525dAS St/St 211PK Aut.	
First Registrationdate:	21/02/2013	Fiscalpower:		
Expertise Mileage:	159478	Power Kw:	155	
Bodytype:	Break	Body color	Dark Brown	
Gearbox:	Automatic	Paint type	Metalic	
Transmission:	Back	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	3119	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Options				
Radio CD		Central consol F		
Windows electric F		Luggage cover		
Windows electric R		Front parking sensors		
Cruise Control		Rear parking sensors		
Steering wheel multifunctional				
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining leather			
Type of climate control	Autom climate control			
Head-up Display				
Level control				
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Summer tyres:	225/55/17/101 W LightMetal			
	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT			404,16	
Bumper R, Scratch(es), Acceptable			0,00	
No pictures to display				
Alloy rim F R, Scratch(es), Acceptable			0,00	
No pictures to display				
Alloy rim R R, Scratch(es), Acceptable			0,00	
No pictures to display				
Ignition key, Missing, E - Replace			150,00	
No pictures to display				
Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)			254,16	



Door F R, Scratch(es), Acceptable

0,00

No pictures to display