



BMW 5 BERLINE: LK5817			
Vinnumber:	WBA5E51060G104550	Versionname:	2.0 520D (140KW)
First Registrationdate:	1/03/2016	Fiscalpower:	
Expertise Mileage:	131690	Power Kw:	140
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	IN 11000	Parking lot	4424
Maintenance	OK		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Options			
Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK
Degree of wear			
Summer tyres:	225/55/17/97 Y LightMetal		
	Fr.L.	Michelin: 6 mm	Fr.R.
	Re.L.	Michelin: 3 mm	Re.R.
		Michelin: 6 mm	Michelin: 3 mm
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			686,88
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)			115,56
Front bumper, Scratch(es), LI - Repair and paint (complete)			254,16



Bumper R, Scratch(es), LI - Repair and paint (complete)	254,16
---	--------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wing R L, Bump(s), PDR - Knock out without painting	63,00
---	-------

