



BMW 5: 1ELW794

Vinnnumber:	WBAXB91070DX44518	Versionname:	5 TOURING 525dXA
First Registrationdate:	17/01/2013	Fiscalpower:	Start/Stop 211PK aut
Expertise Mileage:	114133	Power Kw:	155
Bodytype:		Body color	Anthracite
Gearbox:	Automatic	Paint type	Metalic
Transmission:	4 Wheel	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2315
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	NOT OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/18/96 Y LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	1073,50
-------------------	----------------

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door R L, Bump(s), PDR - Knock out without painting	63,00
---	--------------



Wing R L, Bad repair, Acceptable	0,00
----------------------------------	-------------



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F R, Scratch(es), E - Replace	235,20
---	--------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Front bumper, Bump(s), LI - Repair and paint (complete)	211,80
---	--------



Door R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Sill outer L, Scratch(es), LI - Repair and paint (complete)	310,50
---	--------



Wing R R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Wing R R, Bad repair, Acceptable	0,00
----------------------------------	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display