



BMW 3: 1FWJ257			
Vinnnumber:	WBA3K11030F828520	Versionname:	3 TOURING 318d 136PK
First Registrationdate:	18/11/2013	Fiscalpower:	
Expertise Mileage:	130777	Power Kw:	100
Bodytype:	Break	Body color	Dark Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1115
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Summer tyres:	205/60/16/92 W LightMetal		
	Fr.L.	Michelin: 5 mm	Fr.R.
			Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.
			Michelin: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			0,00
Bumper R, Scratch(es), Acceptable			0,00
No pictures to display			
Front bumper, Scratch(es), Acceptable			0,00
No pictures to display			
Front bumper, Scratch(es), Acceptable			0,00
No pictures to display			
Wing R L, Scratch(es), Acceptable			0,00
No pictures to display			