



BMW 3: 1FWJ777			
Vinnnumber:	WBA3Y11070D448123	Versionname:	3 GRAN TURISMO 318d
First Registrationdate:	18/11/2013	Fiscalpower:	143PK
Expertise Mileage:	149090	Power Kw:	105
Bodytype:		Body color	Dark Blue
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4130
Maintenance	IN 2000KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining leather
Type of climate control	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear			
Winter tyres:	225/55/17/97 H LightMetal		
	Fr.L.	Continental: 4 mm	Fr.R.
	Re.L.	Continental: 6 mm	Re.R.
		Continental: 4 mm	Continental: 6 mm

Assistance equipment	
Repair kit	Yes
Compressor	Yes
Total cost ex VAT	226,20
Windscreen, Stone chip(s), Acceptable	0,00
No pictures to display	
Front bumper, Scratch(es), Acceptable	0,00
No pictures to display	
Door F L, Scratch(es), Acceptable	0,00
No pictures to display	
Trunk lid covering R, Scratch(es), Smart repair	110,64

Tailgate, Bump(s), Acceptable		
0,00		

Language, Sample(s), Reception	0,00
No pictures to display	
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56

