



BMW 3: 1GDN889				
Vinnumber:	WBA3Y51080D155015	Versionname:	3 GRAN TURISMO 320dX 163PK	
First Registrationdate:	8/01/2014	Fiscalpower:		
Expertise Mileage:	100254	Power Kw:	120	
Bodytype:		Body color	Light Blue	
Gearbox:	MAN 6 VIT	Paint type	Metalic	
Transmission:	Back	Rims summer	Aluminium	
Fueltype:	Diesel	Oil level	OK	
Maintenance	IN 8000KM	Parking lot	2612	
Maintenance	OK			
Battery functioning	Yes			
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Aluminium			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
GPS storage	HD	Luggage cover		
GPS storage		Rear parking sensors		
Windows electric F				
Windows electric R				
Cruise Control				
Steering wheel multifunctional				
Type of headlighting	Headlighting Halogen			
Type of GPS	GPS big screen color			
Type of Lining	Lining leather			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Summer tyres:	225/55/17/97 W LightMetal			
	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 5 mm	Re.R.	Bridgestone: 5 mm
Assistance equipment				
Repair kit	Yes	Compressor	Yes	
Total cost ex VAT			211,80	
Tailgate, Scratch(es), Acceptable			0,00	
No pictures to display				
Door frame R R, Bump(s), Acceptable			0,00	
No pictures to display				
Front bumper, Scratch(es), LI - Repair and paint (complete)			211,80	



Alloy rim F L, Scratch(es), Acceptable	0,00
--	------

No pictures to display