



BMW X1: 1NNA227			
Vinnumber:	WBAHT710105E13162	Versionname:	2.0 SDRIVE18D (110KW)
First Registrationdate:	22/03/2016	Fiscalpower:	
Expertise Mileage:	34438	Power Kw:	110
Bodytype:		Body color	Brown
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	4508
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		
Options			
GPS storage		Sun Roof electric	
GPS storage	HD	Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar fixed
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK
Degree of wear			
Winter tyres:	225/50/17/97 H LightMetal		
	Fr.L.	Dunlop: 4 mm	Fr.R.
		Dunlop: 4 mm	
	Re.L.	Dunlop: 7 mm	Re.R.
Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1661,07
Door F R, Scratch(es), LI - Repair and paint (complete)			318,35
Front bumper, Scratch(es), LI - Repair and paint (complete)			211,80



Wheel hub cap R L, Missing, E - Replace	10,00
---	-------



Door R R, Bump(s) and scratch(es), Le - Replace and paint	946,92
---	--------



Protection plate M, Tear, E - Replace	74,00
---------------------------------------	-------



Wing trim R R, Scratch(es), Le - Replace and paint	100,00
--	--------

