


BMW SERIE 3 TOURING: 1HHU310

Vinnnumber:	WBA3K91050F935146	Versionname:	316d
First Registrationdate:	28/07/2014	Fiscalpower:	
Expertise Mileage:	153785	Power Kw:	85
Bodytype:		Body color	Grey
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Back	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	2829
Maintenance	IN 21000 KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Central consol F
GPS storage	HD Luggage cover
GPS storage	
Windows electric F	
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/60/16/92 V LightMetal			
	Fr.L.	Michelin: 7 mm	Fr.R.	Michelin: 7 mm
	Re.L.	Kleber: 7 mm	Re.R.	Kleber: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	180,10
-------------------	---------------

Alloy rim F L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Interior, Damaged, E - Replace	85,10
--------------------------------	--------------





Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Backrest cover F R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Floor covering F L, Worn, P - Check	0,00
-------------------------------------	------



Seat cover F L, Worn, P - Check	0,00
---------------------------------	------



Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Backrest cover F L, Worn, P - Check	0,00
-------------------------------------	------

