



# BMW X1: 1LSB591

|                                   |                          |              |                              |
|-----------------------------------|--------------------------|--------------|------------------------------|
| Vinnnumber:                       | <b>WBAHT71000P908597</b> | Versionname: | <b>2.0 SDRIVE18D (110KW)</b> |
| First Registrationdate:           | <b>19/11/2015</b>        | Fiscalpower: |                              |
| Expertise Mileage:                | <b>37448</b>             | Power Kw:    | <b>110</b>                   |
| Bodytype:                         |                          | Body color   | <b>Blue</b>                  |
| Gearbox:                          | <b>MAN 6 VIT</b>         | Paint type   | <b>Metalic</b>               |
| Transmission:                     |                          | Rims summer  | <b>Aluminium</b>             |
| Fueltype:                         | <b>Diesel</b>            | Oil level    | <b>OK</b>                    |
| Maintenance                       | <b>OK</b>                | Parking lot  | <b>4806</b>                  |
| Battery functioning               | <b>Yes</b>               |              |                              |
| Number of doors                   | <b>5</b>                 |              |                              |
| Number of seats                   | <b>5</b>                 |              |                              |
| Number head rests                 | <b>5</b>                 |              |                              |
| Rims summer                       | <b>Aluminium</b>         |              |                              |
| Category                          | <b>Passenger Car</b>     |              |                              |
| Oil level                         | <b>OK</b>                |              |                              |
| Registration Certificate Car (BE) | <b>Yes</b>               |              |                              |

## Options

|                                |                              |                      |
|--------------------------------|------------------------------|----------------------|
| Radio CD                       |                              | Sun Roof electric    |
| GPS storage                    |                              | Panoramic roof       |
| GPS storage                    | <b>HD</b>                    | Central consol F     |
| Windows electric F             |                              | Luggage cover        |
| Windows electric R             |                              | Rear parking sensors |
| Cruise Control                 |                              |                      |
| Steering wheel multifunctional |                              |                      |
| Type of headlighting           | <b>Headlighting Halogen</b>  |                      |
| Type of GPS                    | <b>GPS big screen color</b>  |                      |
| Type of Lining                 | <b>Lining leather</b>        |                      |
| Type of climate control        | <b>Autom climate control</b> |                      |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

## Degree of wear

|               |                                   |                       |       |                       |
|---------------|-----------------------------------|-----------------------|-------|-----------------------|
|               | <b>225/55/17/92 MS LightMetal</b> |                       |       |                       |
| Winter tyres: | Fr.L.                             | <b>Michelin: 5 mm</b> | Fr.R. | <b>Michelin: 5 mm</b> |
|               | Re.L.                             | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

## Assistance equipment

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|                                               |                |
|-----------------------------------------------|----------------|
| Total cost ex VAT                             | <b>1525,34</b> |
| Bumper moulding F R, Scratch(es), E - Replace | <b>14,40</b>   |



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00

|                                                                                                                                                                                                                                                              |  |  |        |
|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--|--|--------|
|                                                                                              |  |  |        |
| Bumper trim R, Crack, Le - Replace and paint                                                                                                                                                                                                                 |  |  | 150,00 |
|                                                                                            |  |  |        |
| Windscreen, Stone chip(s), Windscreen repair                                                                                                                                                                                                                 |  |  | 58,80  |
|                                                                                            |  |  |        |
| Wing trim R R, Scratch(es), E - Replace                                                                                                                                                                                                                      |  |  | 84,00  |
|                                                                                            |  |  |        |
| Door R R, Scratch(es), LI - Repair and paint (complete)                                                                                                                                                                                                      |  |  | 318,35 |
|    |  |  |        |
| Interior, Dirty, Cleaning                                                                                                                                                                                                                                    |  |  | 50,00  |
|    |  |  |        |
|    |  |  |        |
| Bumper R, Scratch(es), Smart repair                                                                                                                                                                                                                          |  |  | 110,64 |
|    |  |  |        |
| Door trim R R, Scratch(es), E - Replace                                                                                                                                                                                                                      |  |  | 114,00 |
|                                                                                        |  |  |        |
| Wing R R, Bump(s), Acceptable                                                                                                                                                                                                                                |  |  | 0,00   |
| No pictures to display                                                                                                                                                                                                                                       |  |  |        |
| Front bumper, Scratch(es), LI - Repair and paint (complete)                                                                                                                                                                                                  |  |  | 211,80 |



|                                                         |        |
|---------------------------------------------------------|--------|
| Door F R, Scratch(es), LI - Repair and paint (complete) | 318,35 |
|---------------------------------------------------------|--------|

