



CITROEN DS5: 1FBT885

Vinnnumber:	VF7KFRHC8D5504547	Versionname:	DS5 Hybrid4 Chic 163PK Aut.
First Registrationdate:	17/05/2013	Fiscalpower:	
Expertise Mileage:	88119	Power Kw:	120
Bodytype:		Body color	Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	4822
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	
Cruise Control	
Steering wheel multifunction	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/91 H LightMetal			
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2136,95
-------------------	---------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Windscreen, Stone chip(s), E - Replace	0,00
--	------



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)	115,56
--	--------



Wing R R, Bump(s), Acceptable	0,00
-------------------------------	------

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete)	220,18
---	--------



Door F R, Bump(s), PDR - Knock out without painting	63,00
---	-------



Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Maintenance, Maintenance, Execute	0,00
-----------------------------------	------

No pictures to display

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Foglight R, Damaged, E - Replace	138,00
----------------------------------	--------



Front bumper, Scratch(es), LI - Repair and paint (complete)	211,80
---	--------



Door R L, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Door R R, Rust, LI - Repair and paint (complete)	318,35
--	--------



Floor protection F R, Broken, E - Replace	53,36
---	-------

