


**MERCEDES C-CLASSE: 1FLV543**

Vinnumber:	<b>WDD2042021G149681</b>	Versionname:	<b>220CDI BE Edition Avantgarde</b>
First Registrationdate:	<b>12/08/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>114347</b>	Power Kw:	<b>120</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>B1 OVER 125 DAGEN</b>	Parking lot:	<b>4721</b>
Maintenance:	<b>OK</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	<b>HD</b>	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining semi-artificial leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/55/16/91 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>614,60</b>
Mirror side blinker R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door panel R R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Bonnet, Stone chip(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door F L, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Alloy rim F R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)			<b>259,80</b>



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)

259,80



Door R L, Scratch(es), Acceptable

0,00

*No pictures to display*

Alloy rim R L, Scratch(es), Acceptable

0,00

*No pictures to display*