


MERCEDES CLA: 1GN421

Vinnumber:	WDD1173011N076916	Versionname:	CLA BER 200 CDI 136PK
First Registrationdate:	18/03/2014	Fiscalpower:	
Expertise Mileage:	56228	Power Kw:	100
Bodytype:		Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	IN 9 DAGEN SERV B5	Parking lot:	4202
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	367,00
-------------------	--------

Maintenance, Maintenance, Acceptable	0,00
--------------------------------------	------

No pictures to display

Windscreen, Stone chip(s), Windscreen repair	58,80
--	-------



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Door F L, Scratch(es), Acceptable 0,00



Maintenance, Maintenance, Execute 0,00

