



**NISSAN X-Trail: AE2407**

Vinnnumber:	<b>JN1TCNT31U0410840</b>	Versionname:	<b>X-TRAIL 4WD SE ant.scr. 150PK</b>
First Registrationdate:	<b>20/02/2014</b>	Fiscalpower:	<b>150PK</b>
Expertise Mileage:	<b>201707</b>	Power Kw:	<b>110</b>
Bodytype:	<b>Off-road</b>	Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2431</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Windows electric F	Central consol F
Windows electric R	Luggage cover
Steering wheel multifunctional	Type of Tow bar
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>
	<b>Tow bar removable</b>

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>NOT OK</b>

**Degree of wear**

	<b>225/60/17/99 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Continental: 3 mm</b>	Fr.R.	<b>Continental: 3 mm</b>
	Re.L.	<b>Continental: 4 mm</b>	Re.R.	<b>Continental: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	1812,51
Centre console, Damaged, Smart repair	110,64



Rear wiper blade, Damaged, E - Replace	40,00
--	-------



Bumper R, Bump(s), Smart repair	110,64
---------------------------------	--------



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete) 115,56



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Door R R, Scratch(es), LI - Repair and paint (complete) 382,02



Wing F L, Scratch(es), It - Spot repair 115,56



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Wing R L, Scratch(es), Acceptable 0,00

No pictures to display  
Wing F R, Scratch(es), It - Spot repair 115,56



Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), LI - Repair and paint (complete) 264,21



Interior, Dirty, Cleaning 50,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display