



| MERCEDES A: 1JHT508                |                          |              |                            |
|------------------------------------|--------------------------|--------------|----------------------------|
| Vinnumber:                         | <b>WDD1760081V046591</b> | Versionname: | <b>2.1 A 200 CDI STYLE</b> |
| First Registrationdate:            | <b>23/12/2014</b>        | Fiscalpower: |                            |
| Expertise Mileage:                 | <b>89285</b>             | Power Kw:    | <b>100</b>                 |
| Bodytype:                          | <b>Hatchback</b>         | Body color:  | <b>Silver</b>              |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>             |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>           |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                  |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2513</b>                |
| Number of doors:                   | <b>5</b>                 |              |                            |
| Number of seats:                   | <b>5</b>                 |              |                            |
| Number head rests:                 | <b>5</b>                 |              |                            |
| Rims summer:                       | <b>Aluminium</b>         |              |                            |
| Category:                          | <b>Passenger Car</b>     |              |                            |
| Oil level:                         | <b>OK</b>                |              |                            |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                            |

| Options                        |                                       |
|--------------------------------|---------------------------------------|
| Radio CD                       | Central consol F                      |
| Windows electric F             | Luggage cover                         |
| Windows electric R             |                                       |
| Steering wheel multifunctional |                                       |
| Radio multimedia               |                                       |
| Type of headlighting:          | <b>Headlighting Halogen</b>           |
| Type of GPS:                   | <b>GPS big screen color</b>           |
| Type of Lining:                | <b>Lining semi-artificial leather</b> |
| Type of climate control:       | <b>Manual climate control</b>         |

| Limited Technical Inspection |           |                     |            |
|------------------------------|-----------|---------------------|------------|
| Airco functioning            | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile           | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position                | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime          | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass                 | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake                    | <b>OK</b> | Transmission        | <b>OK</b>  |
|                              |           | Lighting            | <b>OK</b>  |
|                              |           | Wiperblades         | <b>OK</b>  |

| Degree of wear |                                  |                          |       |                          |
|----------------|----------------------------------|--------------------------|-------|--------------------------|
|                | <b>205/55/16/92 V LightMetal</b> |                          |       |                          |
| Winter tyres:  | Fr.L.                            | <b>Bridgestone: 4 mm</b> | Fr.R. | <b>Bridgestone: 4 mm</b> |
|                | Re.L.                            | <b>Bridgestone: 5 mm</b> | Re.R. | <b>Bridgestone: 5 mm</b> |

| Assistance equipment                   |            |            |               |
|--|------------|------------|---------------|
| Repair kit                             | <b>Yes</b> | Compressor | <b>Yes</b>    |
| Total cost ex VAT                      |            |            | <b>799,32</b> |
| Alloy rim F L, Scratch(es), Acceptable |            |            | <b>0,00</b>   |
| <i>No pictures to display</i>          |            |            |               |
| Seat cover F L, Damaged, Smart repair  |            |            | <b>64,32</b>  |



|   |               |
|---|---------------|
| Front bumper, Damaged, Le - Replace and paint | <b>735,00</b> |
|---|---------------|



Alloy rim F R, Scratch(es), Acceptable

0,00

*No pictures to display*