



RENAULT Kangoo Express: 1BEK781

Vinnnumber:	VF1FW15H544612616	Versionname:	KANGOO EXPR.B/F MAXI Gr.Confort FAP 90PK
First Registrationdate:	12/05/2011	Fiscalpower:	
Expertise Mileage:	23683	Power Kw:	66
Bodytype:	Transporter	Body color:	White
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4810
Number of doors:	5		
Number of seats:	2		
Number head rests:	2		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		

Options

Radio CD	
Windows electric F	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/95 T Steel			
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment

Spare wheel **Yes**

Total cost ex VAT	1003,84
Wing R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Door R L, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Rearview mirror housing R, Damaged, LI - Repair and paint (complete)	115,56



Wing trim R R, Scratch(es), E - Replace 69,00



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Sill outer R, Scratch(es), Acceptable 0,00

No pictures to display

Trunk door R L, Bump(s) and scratch(es), It - Spot repair 115,56



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 238,76



Rocker panel inner F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 115,56



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Bump(s), Smart repair 110,64

