


PEUGEOT Partner: 1GWA284

Vinnumber:	VF37A9HF0EN517334	Versionname:	PARTNER B/F L1H1 Conf.120 90PK
First Registrationdate:	15/05/2014	Fiscalpower:	
Expertise Mileage:	170452	Power Kw:	66
Bodytype:		Body color	White
Gearbox:	MAN 5 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	LCV21
Maintenance	IN 11200KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	2		
Number head rests	2		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Type of Tow bar	Tow bar fixed
Windows electric F		
Cruise Control		
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Winter tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Pirelli: 2 mm	Re.R.	Pirelli: 2 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1119,92
-------------------	----------------

Seat cover F L, Stain, Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Protection plate M, Hole, E - Replace	35,00
---------------------------------------	--------------



Wheel cover F L, Damaged, E - Replace	22,50
---------------------------------------	--------------





Sliding door R, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Bodywork, Not original part, Acceptable 0,00

No pictures to display


Wheel cover F R, Damaged, E - Replace 22,50



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Damaged, E - Replace 0,00



Wing F R, Bump(s), PDR - Knock out without painting 63,00



Sill outer R, Bump(s), LI - Repair and paint (complete) 232,88



Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete) 362,02

