



PEUGEOT 2008: 1GKP358			
Vinnnumber:	VF3CU9HP0DY045641	Versionname:	2008 e-HDi Active 92PK
First Registrationdate:	4/03/2014	Fiscalpower:	
Expertise Mileage:	77649	Power Kw:	68
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:		Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4101
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear				
	195/60/16/89 H Steel			
Summer tyres:	Fr.L.	Bridgestone: 6 mm	Fr.R.	Bridgestone: 6 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes

Total cost ex VAT	322,78
-------------------	--------

Wheel cover F R, Scratch(es), Acceptable	0,00
--	------

<i>No pictures to display</i>	
Wing R R, Bump(s), PDR - Knock out without painting	102,60



Wing F R, Bump(s), L.L. Repair and paint (complete)	320,48
---	--------

