



| | | | |
|-----------------------------|--------------------------|--------------|---------------------------|
| PEUGEOT 308: 1ENW839 | | | |
| Vinnnumber: | VF34E9HP0CS268714 | Versionname: | 308 SW Access 92PK |
| First Registrationdate: | 4/02/2013 | Fiscalpower: | |
| Expertise Mileage: | 174319 | Power Kw: | 68 |
| Bodytype: | Break | Body color: | White |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1325 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Steel | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |

| | |
|--------------------------|-------------------------------|
| Options | |
| Radio CD | Luggage cover |
| Windows electric F | Rear parking sensors |
| Cruise Control | |
| Type of headlighting: | Headlighting Halogen |
| Type of Lining: | Lining fabrics |
| Type of climate control: | Manual climate control |

| | | | |
|-------------------------------------|-----------|---------------------|---------------|
| Limited Technical Inspection | | | |
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | NOT OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

| | | | | |
|-----------------------|-----------------------------|--------------------|-------|--------------------|
| Degree of wear | | | | |
| | 195/65/15/91 H Steel | | | |
| Summer tyres: | Fr.L. | Fulda: 4 mm | Fr.R. | Fulda: 4 mm |
| | Re.L. | Fulda: 3 mm | Re.R. | Fulda: 3 mm |

| | |
|---|---------|
| Assistance equipment | |
| Total cost ex VAT | 1825,08 |
| Wing R R, Bump(s), LI - Repair and paint (complete) | 308,20 |



| | |
|---|-------|
| Wheel cover R L, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Wheel cover F R, Scratch(es), E - Replace | 30,00 |



Wheel cover F L, Scratch(es), E - Replace 30,00



Door F L, Bump(s), LI - Repair and paint (complete) 318,35



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Roof, Bump(s), Acceptable 0,00

No pictures to display

Interior, Dirty, Cleaning 50,00



Wheel cover R R, Scratch(es), E - Replace 30,00



Wing F L, Scratch(es), LI - Repair and paint (complete) 220,18

