



**OPEL Insignia: 1ERJ462**

Vinnnumber:	<b>WOLGS8EL9D1066720</b>	Versionname:	<b>INSIGNIA BRE ecofi.Sport S/S DPF 130PK</b>
First Registrationdate:	<b>1/03/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>191837</b>	Power Kw:	<b>96</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3526</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	<b>SD</b>	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>NOT OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>245/45/18/96 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Continental: 6 mm</b>	Fr.R.	<b>Continental: 6 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-------------	------------	------	------------

Total cost ex VAT	<b>1860,58</b>
-------------------	----------------

Wing R R, Scratch(es), Acceptable	<b>0,00</b>
-----------------------------------	-------------

*No pictures to display*



Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	<b>211,80</b>
---	---------------



Door R R, Bump(s), PDR - Knock out without painting	<b>63,00</b>
---	--------------

	Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
---	--	-------



	Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)	301,68
---	---	--------

	Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
Alloy rim F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
	Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20

	Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	---	--------

	Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	---	--------

	Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
--	---	--------

	Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Bumper grille, Damaged, E - Replace	32,40

		
---	--	--

	Door F L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>		
	Bumper grille, Damaged, E - Replace	32,40

