


RENAULT Grand Scenic: 1EMN776

Vinnnumber:	VF1JZ14B648442285	Versionname:	GR.SCENIC Energ.Dynamique 7pl.FAP 110PK
First Registrationdate:	23/01/2013	Fiscalpower:	
Expertise Mileage:	157924	Power Kw:	81
Bodytype:	MPV	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2227
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS base
Type of Lining	Lining semi-artificial leather
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/95 V LightMetal				
Summer tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Uniroyal: 5 mm	Re.R.	Uniroyal: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1226,34
-------------------	---------

Bonnet, Bad repair, Acceptable	0,00
--------------------------------	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door trim F R, Scratch(es), E - Replace	114,00
---	--------




Roof, Bump(s), LI - Repair and paint (complete) 577,50



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s) and scratch(es), It - Spot repair 115,56



Seat cover F L, Worn, Acceptable 0,00

No pictures to display

Internal Boot Lining L, Damaged, Smart repair 110,64



Seat belt R R, Damaged, Forfeit 198,00



Internal Boot Lining R, Damaged, Smart repair 110,64

