


RENAULT Grand Scenic: 1GTH842

Vinnnumber:	VF1JZNAB650736286	Versionname:	GRAND SCENIC Energy Intens 7pl.130PK
First Registrationdate:	24/04/2014	Fiscalpower:	
Expertise Mileage:	53803	Power Kw:	96
Bodytype:		Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	1714
Number of doors	5		
Number of seats	7		
Number head rests	7		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Sun Roof electric	
GPS storage		Panoramic roof	
GPS storage	SD	Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunction		Type of Tow bar	Tow bar fixed
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/17/95 V LightMetal			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm






Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1528,22
Rearview mirror housing R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim R R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Roof rail R, Incomplete, E - Replace			74,00



Door R R, Scratch(es), LI - Repair and paint (complete)

382,02

		
		
Roof rail L, Incomplete, E - Replace		74,00
		
Bumper R, Scratch(es), LI - Repair and paint (complete)		254,16
		
Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete)		382,02
		
Alloy rim F R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Windscreen, Repaired, Acceptable		0,00
<i>No pictures to display</i>		
Alloy rim R L, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Front bumper, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Trunk lid covering R, Scratch(es), Acceptable		0,00
<i>No pictures to display</i>		
Tailgate, Bump(s) and scratch(es), LI - Repair and paint (complete)		362,02
