


**RENAULT Grand Scenic: 1FCT481**

Vinnnumber:	<b>VF1JZ14M649035096</b>	Versionname:	<b>GRAND SCENIC Expression</b>
First Registrationdate:	<b>27/05/2013</b>	Fiscalpower:	<b>5pl.110PK</b>
Expertise Mileage:	<b>178280</b>	Power Kw:	<b>81</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4502</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

**Options**

Radio CD		Luggage cover	
GPS storage	<b>SD</b>	Rear parking sensors	
GPS storage		Type of Tow bar	<b>Tow bar fixed</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

205/60/16/92 H Steel				
Summer tyres:	Fr.L.	<b>Continental: 3 mm</b>	Fr.R.	<b>Continental: 3 mm</b>
	Re.L.	<b>Continental: 3 mm</b>	Re.R.	<b>Continental: 3 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
Total cost ex VAT			<b>123,00</b>
Wheel cover F R, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door R L, Bump(s), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Wheel cover R R, Damaged, Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Door R R, Bump(s) and scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Interior, Dirty, Cleaning			<b>60,00</b>



Door F R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing R L, Bump(s), PDR - Knock out without painting	63,00



Rocker panel inner R L, Damaged, Acceptable	0,00
<i>No pictures to display</i>	
Windscreen, Repaired, Acceptable	0,00

