


OPEL Astra: 1EZB403

Vinnnumber:	W0LPD8EW2D8052086	Versionname:	ASTRA BRE ecoFL.Enjoy Active St/St 110PK
First Registrationdate:	25/04/2013	Fiscalpower:	
Expertise Mileage:	67501	Power Kw:	81
Bodytype:		Body color	Brown
Gearbox:	MAN 6 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3110
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

215/60/16/99 H Steel				
Winter tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 3 mm	Re.R.	Bridgestone: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	2230,40
-------------------	---------

Rearlight L, Broken, E - Replace	114,00
----------------------------------	--------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Floor covering F L, Hole, Acceptable	0,00
--------------------------------------	------

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Rearlight R , Scratch(es), E - Replace 114,00



Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Bumper R, Broken, Le - Replace and paint 651,00



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Stain, Acceptable 0,00

No pictures to display

Front bumper, Broken, Le - Replace and paint 735,00

