



RENAULT Megane: 1GUH301			
Vinnnumber:	<b>VF1KZ0R0250421799</b>	Versionname:	<b>MEGANE GT TomTom Edition 95PK</b>
First Registrationdate:	<b>2/05/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>171464</b>	Power Kw:	<b>70</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2230</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

Options	
Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>


Degree of wear				
	<b>205/55/16/91 V Steel</b>			
Summer tyres:	Fr.L.	<b>Hankook: 6 mm</b>	Fr.R.	<b>Hankook: 6 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

Assistance equipment	
Repair kit	<b>Yes</b>
Compressor	<b>Yes</b>
Total cost ex VAT	3303,46
Wing R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Roof, Hail damage, PDR - Hail	1300,00





Bonnet, Hail damage, PDR - Hail 375,00



Roof, Chemical polution, LI - Repair and paint (complete) 481,50




Interior, Dirty, Cleaning 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35




Wing R L, Bump(s), Acceptable 0,00

No pictures to display 0,00

Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 220,18



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display