



PEUGEOT 508: 1FCY710

Vinnnumber:	VF38URHC8DL018827	Versionname:	508 SW RXH BMP STT 163PK Aut.
First Registrationdate:	28/05/2013	Fiscalpower:	
Expertise Mileage:	80364	Power Kw:	120
Bodytype:	Break	Body color:	Brown
Gearbox:	Automatic	Paint type:	Metalic
Transmission:		Rims summer:	Aluminium
Fueltype:	Hybrid Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1716
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Type of headlighting	Headlighting Halogen	Rear parking sensors	
Type of GPS	GPS big screen color	Type of Tow bar	Tow bar removable
Type of Lining	Lining semi-leather		
Type of climate control	Autom climate control		
Head-up Display			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	245/45/18/96 W LightMetal			
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

	Runflat	Yes
Total cost ex VAT		1474,11
Bumper R, Scratch(es), LI - Repair and paint (complete)		211,80



Wing R L, Chemical polution, LI - Repair and paint (complete)

308,20



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00




Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), E - Replace 235,20



Wing R R, Scratch(es), It - Spot repair 115,56





Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00

