


RENAULT Grand Scenic: 1FBT909

Vinnnumber:	VF1JZ00AD48739725	Versionname:	GR.SCENIC Energ.Bose
First Registrationdate:	17/05/2013	Fiscalpower:	Edit.5pl.FAP 130PK
Expertise Mileage:	139548	Power Kw:	96
Bodytype:		Body color:	Red
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	VERVERSEN	Parking lot:	2226
Maintenance:	NOT OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Sun Roof electric	
GPS storage	SD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather and alcantara		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 V LightMetal			
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Continental: 5 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm



















Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1294,40
-------------------	---------

Door R L, Bump(s) and scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Seat cover F L, Hole, Smart repair	64,32
	
Tailgate, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Dashboard, Worn, Acceptable	0,00
	
Door F R, Bump(s), PDR - Knock out without painting	63,00
	
Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
	
	
	
Front bumper, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F L, Scratch(es), LI - Repair and paint (complete)	220,18
	
	
	
Door frame R L, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L polished, Damaged, E - Replace	235,20
	
	
	
Maintenance, Maintenance, Execute	0,00



Door frame R R, Bump(s) and scratch(es), Acceptable	0,00
---	------

No pictures to display

Cupholder, Broken, E - Replace	75,00
--------------------------------	-------



Alloy rim F L polished, Scratch(es), Acceptable	0,00
---	------

No pictures to display