



VOLKSWAGEN Golf: 1FEF221			
Vinnnumber:	<b>WVWZZZ1KZDM684632</b>	Versionname:	<b>GOLF BRE Trendline BlueMot.DPF 105PK</b>
First Registrationdate:	<b>5/06/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>154618</b>	Power Kw:	<b>77</b>
Bodytype:	<b>Break</b>	Body color	<b>Light Grey</b>
Gearbox:	<b>MAN 5 VIT</b>	Paint type	<b>Metalic</b>
Transmission:		Rims summer	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>4504</b>
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		




Options	
Radio CD	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>205/55/16/91 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Kleber: 6 mm</b>	Fr.R.	<b>Kleber: 6 mm</b>
	Re.L.	<b>Kleber: 6 mm</b>	Re.R.	<b>Kleber: 6 mm</b>

Assistance equipment			
Spare wheel	<b>Yes</b>	Jack	<b>Yes</b>

Total cost ex VAT	568,76
Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	308,20

			
Alloy rim R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)			115,56



Alloy rim F R, Scratch(es), Acceptable	0,00
--	------

*No pictures to display*

Alloy rim F L, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Interior, Dirty, Cleaning	0,00
---------------------------	------



Interior, Dirty, Cleaning	50,00
---------------------------	-------

*No pictures to display*