



VOLKSWAGEN Golf: 1H7V796

Vinnumber:	WVWZZZAUZFP547677	Versionname:	GOLF VAR Trendline 105PK
First Registrationdate:	1/10/2014	Fiscalpower:	
Expertise Mileage:	154588	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3405
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage	HD	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/92 MS Steel			
Winter tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1117,60
-------------------	----------------

Wing R L, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Wing F R, Bump(s), LI - Repair and paint (complete)	220,18
---	---------------



Interior, Dirty, Cleaning	36,00
---------------------------	--------------



Sill outer R, Bump(s), LI - Repair and paint (complete) 310,50



Bonnet, Chemical polution, Acceptable 0,00



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Roof, Chemical polution, Acceptable 0,00



Bonnet, Bump(s), PDR - Knock out without painting 63,00



Ceiling, Hole, Smart repair 64,32



Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80

