



VOLKSWAGEN Golf: 1DLK513

Vinnnumber:	WVWZZZ1KZDW007611	Versionname:	GOLF BER BlueMotion DPF
First Registrationdate:	15/06/2012	Fiscalpower:	105PK
Expertise Mileage:	203364	Power Kw:	77
Bodytype:		Body color	Light Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:		Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2433
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	
Steering wheel multifunctional	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H LightMetal			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	145,00
-------------------	---------------

Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Door R R, Bump(s), Acceptable	0,00
-------------------------------	-------------

No pictures to display

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Cupholder R, Damaged, E - Replace	50,00
-----------------------------------	--------------



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display