



TOYOTA AYGO: YX7378			
Vinnumber:	<b>JTDKGN20N201065</b>	Versionname:	<b>1.0 VVT-I X-PLAY MMT</b>
First Registrationdate:	<b>11/01/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>21792</b>	Power Kw:	<b>51</b>
Bodytype:	<b>Hatchback</b>	Body color	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Steel</b>
Fueltype:	<b>Petrol</b>	Oil level	<b>OK</b>
Battery functioning	<b>Yes</b>	Parking lot	<b>3632</b>
Number of doors	<b>5</b>		
Number of seats	<b>4</b>		
Number head rests	<b>2</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		


Options	
Radio CD	Luggage cover
Windows electric F	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining fabrics</b>
Type of climate control	<b>Manual climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>165/60/15/77 T Steel</b>			
Winter tyres:	Fr.L.	<b>Semperit: 4 mm</b>	Fr.R.	<b>Semperit: 4 mm</b>
	Re.L.	<b>Semperit: 5 mm</b>	Re.R.	<b>Semperit: 5 mm</b>

Assistance equipment			
Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>

Total cost ex VAT	597,34
Roof, Chemical pollution, LI - Repair and paint (complete)	385,20



Wing R R, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Scratch(es), LI - Repair and paint (complete)	176,14



Aerial, Damaged, E - Replace	12,00
------------------------------	-------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Wheel cover F R, Scratch(es), E - Replace	24,00
---	-------



Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*