



VOLKSWAGEN Polo: 1HLR197				
Vinnumber:	WVWZZZ6RZFY044346	Versionname:	POLO Trendline BMT 75PK	
First Registrationdate:	21/08/2014	Fiscalpower:		
Expertise Mileage:	188174	Power Kw:	55	
Bodytype:	Hatchback	Body color	Black	
Gearbox:	MAN 5 VIT	Paint type	Metalic	
Transmission:	Front	Rims summer	Steel	
Fueltype:	Diesel	Oil level	OK	
Battery functioning	Yes	Parking lot	1431	
Number of doors	5			
Number of seats	5			
Number head rests	5			
Rims summer	Steel			
Category	Passenger Car			
Oil level	OK			
Registration Certificate Car (BE)	Yes			
Options				
Radio CD		Central consol F		
Windows electric F		Luggage cover		
Radio multimedia				
Type of headlighting	Headlighting Halogen			
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Airco functioning	OK	Battery functioning	Yes	
Tires wear profile	OK	Power steering	Yes	
Idle position	OK	Sound engine	OK	
Engine startingtime	OK	Clutch test	OK	
Exhaust gass	OK	Wiper fluid level	OK	
Handbrake	OK	Transmission	OK	
		Lighting	OK	
		Wiperblades	OK	
Degree of wear				
Summer tyres:	175/70/14/84 T Steel			
	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm
Assistance equipment				
Spare wheel	Yes	Jack	Yes	
Total cost ex VAT			626,68	
Door R R, Scratch(es), LI - Repair and paint (complete)			254,68	
				
				
Wing R L, Scratch(es), Acceptable			0,00	
No pictures to display				
Front bumper, Scratch(es), Acceptable			0,00	
No pictures to display				
Wheel cover F R, Scratch(es), E - Replace			24,00	



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Roof, Bump(s), PDR - Knock out without painting	63,00
---	-------



Bumper R, Scratch(es), LI - Repair and paint (complete)	169,44
---	--------



Wing F L, Bump(s) and scratch(es), It - Spot repair	115,56
---	--------

