



VOLKSWAGEN Polo: 1HBR425

Vinnnumber:	WVWZZZ6RZFY063178	Versionname:	POLO Comfortline BMT
First Registrationdate:	12/06/2014	Fiscalpower:	90PK
Expertise Mileage:	103543	Power Kw:	66
Bodytype:		Body color:	Dark Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	4230
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Front parking sensors
Windows electric R		Rear parking sensors
Cruise Control		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Manual climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

	185/60/15/84 H Steel			
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	238,44
Engine protective plate, Hole, E - Replace	45,00



Sill outer L, Bump(s), It - Spot repair	0,00
---	------



Bumper R, Scratch(es), LI - Repair and paint (complete)

169,44



Roof, Hail damage, PDR - Hail

0,00



Door R L, Bump(s) and scratch(es), Le - Replace and paint

0,00



Wheel cover F R, Missing, E - Replace

24,00



Interior, Smell, Ozone treatment

0,00



Front bumper, Scratch(es), Acceptable

0,00

No pictures to display

Door F L, Bump(s), PDR - Knock out without painting

0,00



Wing R R, Hail damage, PDR - Hail

0,00



