



## VOLKSWAGEN Caddy: 1DPL097

|                         |                          |              |                                 |
|-------------------------|--------------------------|--------------|---------------------------------|
| Vinnnumber:             | <b>WV2ZZZ2KZCX158780</b> | Versionname: | <b>CADDY LIFE Baseline 75PK</b> |
| First Registrationdate: | <b>13/07/2012</b>        | Fiscalpower: |                                 |
| Expertise Mileage:      | <b>209990</b>            | Power Kw:    | <b>55</b>                       |
| Bodytype:               | <b>Hatchback</b>         | Body color:  | <b>White</b>                    |
| Gearbox:                | <b>MAN 5 VIT</b>         | Paint type:  | <b>Opaque</b>                   |
| Transmission:           | <b>Front</b>             | Rims summer: | <b>Steel</b>                    |
| Fueltype:               | <b>Diesel</b>            | Oil level:   | <b>OK</b>                       |
| Maintenance:            | <b>OK</b>                | Parking lot: | <b>4219</b>                     |
| Battery functioning:    | <b>Yes</b>               |              |                                 |
| Number of doors:        | <b>4</b>                 |              |                                 |
| Number of seats:        | <b>5</b>                 |              |                                 |
| Number head rests:      | <b>5</b>                 |              |                                 |
| Rims summer:            | <b>Steel</b>             |              |                                 |
| Category:               | <b>Passenger Car</b>     |              |                                 |
| Oil level:              | <b>OK</b>                |              |                                 |

## Options

|                      |                                  |
|----------------------|----------------------------------|
| Radio CD             |                                  |
| Type of headlighting | <b>Headlighting Halogen</b>      |
| Type of Lining       | <b>Lining artificial leather</b> |

## Limited Technical Inspection

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

## Degree of wear

|               |                             |                       |       |                       |
|---------------|-----------------------------|-----------------------|-------|-----------------------|
|               | <b>195/65/15/91 T Steel</b> |                       |       |                       |
| Summer tyres: | Fr.L.                       | <b>Uniroyal: 6 mm</b> | Fr.R. | <b>Uniroyal: 6 mm</b> |
|               | Re.L.                       | <b>Pirelli: 5 mm</b>  | Re.R. | <b>Pirelli: 5 mm</b>  |

## Assistance equipment

|             |            |      |            |
|-------------|------------|------|------------|
| Spare wheel | <b>Yes</b> | Jack | <b>Yes</b> |
|-------------|------------|------|------------|

|                               |       |
|-------------------------------|-------|
| Total cost ex VAT             | 40,00 |
| Ashtray, Missing, E - Replace | 20,00 |



|                                       |       |
|---------------------------------------|-------|
| Bumper R, Scratch(es), Acceptable     | 0,00  |
| <i>No pictures to display</i>         |       |
| Bonnet, Stone chip(s), Acceptable     | 0,00  |
| <i>No pictures to display</i>         |       |
| Wing R R, Scratch(es), Acceptable     | 0,00  |
| <i>No pictures to display</i>         |       |
| Windscreen, Stone chip(s), Acceptable | 0,00  |
| <i>No pictures to display</i>         |       |
| Mats, Incomplete, E - Replace         | 20,00 |



Dashboard, Hole, Acceptable

0,00

