


TOYOTA GRAND PRIUS+: 1NKJ579

Vinnnumber:	JTDZS3EU20J008352	Versionname:	1.8 VVT-I HYBRID ACTIVE
First Registrationdate:	13/05/2016	Fiscalpower:	AUTO
Expertise Mileage:	63905	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Hybrid Petrol	Oil level:	OK
Maintenance:	OK	Parking lot:	4724
Maintenance:	GEEN MELDING		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 H Steel			
Winter tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1063,46
-------------------	---------

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper trim R, Scratch(es), E - Replace	208,71
---	--------





Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Worn, Acceptable 0,00



Door F L, Scratch(es), LI - Repair and paint (complete) 318,35



Wing F R, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace 30,00



Wheel cover R R, Scratch(es), Acceptable 0,00

No pictures to display

Roof pillar R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing F L, Scratch(es), Acceptable 0,00

No pictures to display

Roof, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Bump(s), PDR - Knock out without painting 82,80



Wheel cover R L, Scratch(es), Acceptable

0,00

No pictures to display