



VOLKSWAGEN TIGUAN: 1EWM297

Vinnnumber:	WVGZZ5NZDW609433	Versionname:	TIGUAN Trend&Fun BM Tech.110PK
First Registrationdate:	8/04/2013	Fiscalpower:	
Expertise Mileage:	192691	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2629
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD		Sun Roof electric	
GPS storage	HD	Panoramic roof	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Type of Tow bar	Tow bar fixed
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/65/16/98 H LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 8 mm	Fr.R.	Uniroyal: 8 mm
	Re.L.	Uniroyal: 0 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	358,20
Wing R L, Scratch(es), LI - Repair and paint (complete)	308,20



Rearview mirror housing R, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Interior, Stain, Cleaning	50,00
---------------------------	-------



Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Boot carpet, Waterinfiltration, P - Check	0,00
---	------



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Trunk lid covering R, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Rear spoiler, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Tailgate, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display