



VOLKSWAGEN Touran: 1GWX967			
Vinnnumber:	WVGZZZ1TZEW099889	Versionname:	TOURAN Highline BMT St/St 7pl.DSG 105PK
First Registrationdate:	22/05/2014	Fiscalpower:	
Expertise Mileage:	34940	Power Kw:	77
Bodytype:	MPV	Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4702
Number of doors:	5		
Number of seats:	7		
Number head rests:	7		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	Tow bar fixed
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		



Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 X LightMetal			
Summer tyres:	Fr.L.	Michelin: 3 mm	Fr.R.	Michelin: 3 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment	
Total cost ex VAT	1236,88
Front bumper, Bump(s) and scratch(es), Le - Replace and paint	735,00



Rearview mirror housing L, Scratch(es), Acceptable	0,00
--	------

Tailgate, Bump(s), Acceptable	0,00
<i>No pictures to display</i>	
Bumper R, Bump(s), LI - Repair and paint (complete)	211,80
	
Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
	
Wing F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	