



VOLVO V40: 1GBF479

Vinnumber:	YV1MV8481E2125092	Versionname:	V40 D2 Base 115PK
First Registrationdate:	13/12/2013	Fiscalpower:	
Expertise Mileage:	151483	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	SERVICE IN 9440KM 6M	Parking lot:	3604
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L
GPS storage		Central consol F
GPS storage	HD	Luggage cover
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	Headlighting Halogen	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 Y LightMetal			
Summer tyres:	Fr.L.	Vredestein: 7 mm	Fr.R.	Vredestein: 7 mm
	Re.L.	Uniroyal: 4 mm	Re.R.	Uniroyal: 4 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	694,80
-------------------	--------

Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Front bumper, Bump(s) and scratch(es), LI - Repair and paint (complete)	259,80
-------------------------------------------------------------------------	--------





Alloy rim R R, Scratch(es), LI - Repair and paint (complete) 95,00



Door R R, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim F L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Ignition key, Missing, E - Replace 150,00



Interior, No damage, Acceptable 0,00



Bumper trim R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Bump(s), Acceptable 0,00

No pictures to display

Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Seat cover R R, Deformed, Acceptable 0,00

No pictures to display

Door F R, Bump(s), Acceptable 0,00

No pictures to display