



VOLVO V60: 1FBP128			
Vinnumber:	<b>YV1GWAAS0D1137192</b>	Versionname:	<b>V60 D6 AWD Plug-in Hybr.Pure L.Ed.215PK</b>
First Registrationdate:	<b>16/05/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>95894</b>	Power Kw:	<b>158</b>
Bodytype:	<b>Break</b>	Body color:	<b>Light Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Hybrid Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1308</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

Options	
Radio CD	Seats electric F L
Windows electric F	Seats electric F R
Windows electric R	Sun Roof electric
Cruise Control	Central consol F
Steering wheel multifunction	Luggage cover
Seats F heated	Front parking sensors
Radio multimedia	Rear parking sensors
Type of headlighting	<b>Headlighting Halogen</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

Limited Technical Inspection			
Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

Degree of wear				
	<b>235/45/17/97 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Pirelli: 7 mm</b>	Fr.R.	<b>Pirelli: 7 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

Assistance equipment	
Number of charging cables (normal)	<b>1</b>

Total cost ex VAT	<b>540,75</b>
Door F L, Rust, LI - Repair and paint (complete)	<b>318,35</b>



Bumper R, Scratch(es), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Wing R R, Bump(s), Acceptable	<b>0,00</b>
<i>No pictures to display</i>	
Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	<b>95,00</b>



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	-------



Front bumper, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Bumper grille, Damaged, E - Replace	32,40
-------------------------------------	-------

