



VOLVO V60: 1HFB601

Vinnumber:	YV1FW31A0F1226847	Versionname:	V60 BRE D3 Kinetic Geartr.136PK Aut.
First Registrationdate:	4/07/2014	Fiscalpower:	
Expertise Mileage:	121175	Power Kw:	100
Bodytype:		Body color	Light Brown
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	4111
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/50/17/91 W LightMetal			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	1855,46
-------------------	----------------

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete)	452,20
---	---------------



Maintenance, Maintenance, Execute 0,00



Outer door handle F R, Scratch(es), LI - Repair and paint (complete) 115,56



Door R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35



Bumper R, Damaged, Le - Replace and paint 651,00



Door F R, Bump(s) and scratch(es), LI - Repair and paint (complete) 318,35

