



VOLVO V40: 1FBE111

Vinnnumber:	YV1MZ8451D2009884	Versionname:	V40 Cr.Country D2 Base 115PK
First Registrationdate:	14/05/2013	Fiscalpower:	
Expertise Mileage:	141875	Power Kw:	84
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2313
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Windows electric F	Central consol F	
Windows electric R	Luggage cover	
Cruise Control	Rear parking sensors	
Radio multimedia	Type of Tow bar	Tow bar removable
Type of headlighting	Headlighting Halogen	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/92 V LightMetal			
Summer tyres:	Fr.L.	Uniroyal: 6 mm	Fr.R.	Uniroyal: 6 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	115,56
-------------------	---------------

Sill outer R, Stain, Acceptable	0,00
---------------------------------	-------------

No pictures to display

Wing R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door F L, Bad repair, Acceptable	0,00
----------------------------------	-------------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	-------------

No pictures to display

Bumper R, Scratch(es), It - Spot repair	115,56
---	---------------



Bumper F L, Stone chip(s), Acceptable

0,00

No pictures to display