



## AUDI A7: 1EUC706

Vinnnumber:	<b>WAUZZZ4G1DN121117</b>	Versionname:	<b>A7 S8 Multitr. 204PK Aut.</b>
First Registrationdate:	<b>1/01/2020</b>	Fiscalpower:	
Expertise Mileage:	<b>75781</b>	Power Kw:	<b>150</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2129</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>4</b>		
Number head rests:	<b>4</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		

## Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Windows electric R	Front parking sensors
Cruise Control	Rear parking sensors
Steering wheel multifunction	
Seats F heated	
Radio multimedia	
Type of headlighting	<b>Headlighting Xenon</b>
Type of GPS	<b>GPS big screen color</b>
Type of Lining	<b>Lining leather</b>
Type of climate control	<b>Autom climate control</b>

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear


	<b>235/55/17/99 Y LightMetal</b>			
Summer tyres:	Fr.L.	<b>Bridgestone: 3 mm</b>	Fr.R.	<b>Bridgestone: 3 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			363,00
Bumper R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Registration Document, Missing, E - Replace			150,00
<i>No pictures to display</i>			
Ignition key, Missing, E - Replace			150,00
<i>No pictures to display</i>			
Wing R R, Bad repair, Acceptable			0,00



Bonnet, Bump(s), PDR - Knock out without painting 63,00



Bonnet, Scratch(es), Acceptable 0,00

No pictures to display