



AUDI A3: 1GBC252

Vinnumber:	WAUZZZ8V4EA107634	Versionname:	
First Registrationdate:	12/12/2013	Fiscalpower:	
Expertise Mileage:	171974	Power Kw:	
Bodytype:	Hatchback	Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	No		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar fixed
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 7 mm	Re.R.	Goodyear: 7 mm

Assistance equipment

Spare wheel	No	Jack	No
-------------	-----------	------	-----------

Total cost ex VAT	1659,58
Seat cover F L, Tear, E - Replace	360,00



Alloy rim F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Wing F R, Bump(s) and scratch(es), LI - Repair and paint (complete)	220,18



Front bumper, Scratch(es), LI - Repair and paint (complete) 211,80



Interior, Dirty, Cleaning 25,00



Spare wheel, Missing, E - Replace 196,80



Windscreen trim, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete) 211,80



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Jack, Missing, E - Replace	42,00
----------------------------	-------



Windscreen, Stone chip(s), Windscreen repair	58,80
--	-------



Interior, Stain, Cleaning	25,00
---------------------------	-------

