



AUDI A6: 1FBE102			
Vinnumber:	WAUZZZ4G2DN147404	Versionname:	A6 AVANT 163PK
First Registrationdate:	14/05/2013	Fiscalpower:	
Expertise Mileage:	115301	Power Kw:	120
Bodytype:	Break	Body color:	Dark Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	1230
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options	
Radio CD	Central consol F
TV/DVD screen R	Luggage cover
Windows electric F	Front parking sensors
Windows electric R	Rear parking sensors
Cruise Control	
Steering wheel multifunctional	
Seats F heated	
Radio multimedia	
Type of headlighting	Headlighting Xenon
Type of GPS	GPS big screen color
Type of Lining	Lining leather
Type of climate control	Autom climate control


Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	225/55/17/101 V LightMetal			
Winter tyres:	Fr.L.	Goodyear: 3 mm	Fr.R.	Goodyear: 3 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm

Assistance equipment			
Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1538,04
Front bumper, Scratch(es), LI - Repair and paint (complete)			254,16



Bonnet, Bad repair, Acceptable			0,00
--------------------------------	--	--	-------------



Rear window, Scratch(es), E - Replace 0,00



Door R L, Chemical polution, LI - Repair and paint (complete) 382,02



Ignition key, Missing, E - Replace 150,00

No pictures to display

Door F L, Chemical polution, LI - Repair and paint (complete) 382,02



Wing R R, Scratch(es), LI - Repair and paint (complete) 369,84



Rear spoiler, Scratch(es), Acceptable 0,00

No pictures to display