



AUDI A3: 1GXC596			
Vinnumber:	WAUZZZ8V5EA192905	Versionname:	A3 SB Ultra Attraction
First Registrationdate:	23/05/2014	Fiscalpower:	110PK
Expertise Mileage:	81425	Power Kw:	81
Bodytype:	Hatchback	Body color:	Dark Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3109
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options	
Radio CD	Luggage cover
Windows electric F	Rear parking sensors
Windows electric R	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting:	Headlighting Xenon
Type of GPS:	GPS big screen color
Type of Lining:	Lining fabrics
Type of climate control:	Autom climate control

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 7 mm	Re.R.	Michelin: 7 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes

Total cost ex VAT	2484,06
Bumper R, Bump(s) and scratch(es), LI - Repair and paint (complete)	211,80




Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	---------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Door R L, Chemical polution, LI - Repair and paint (complete) 318,35



Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Interior, Smell, Ozone treatment 152,58



Wing R L, Chemical polution, LI - Repair and paint (complete) 308,20



Door R R, Scratch(es), LI - Repair and paint (complete) 318,35



Tailgate, Bump(s), Acceptable 0,00

No pictures to display

Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 308,20

