


**AUDI A6: 1JKF648**

Vinnnumber:	<b>WAUZZZ4G7EN203810</b>	Versionname:	<b>A6 BER Multitr.136PK Aut.</b>
First Registrationdate:	<b>8/01/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>111787</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Dark Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4732</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	<b>Tow bar fixed</b>
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>NOT OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>225/55/17/97 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 5,5 mm</b>	Re.R.	<b>Michelin: 5,5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

**Total cost ex VAT** 2220,46

**Alloy rim R L, Scratch(es), LI - Repair and paint (complete)** 95,00

**Wheel arch cover F L, Broken, E - Replace**
**75,00**



Door F L, Bump(s) and scratch(es), LI - Repair and paint (complete) 382,02



Wing R R, Bump(s) and scratch(es), LI - Repair and paint (complete) 369,84



Alloy rim F L, Damaged, E - Replace 277,44



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16



Front bumper, Scratch(es), LI - Repair and paint (complete) 254,16



Wing R L, Bump(s) and scratch(es), LI - Repair and paint (complete) 417,84



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00

